



## PLASMA BUSHING GUIDE

Bushing O.D. 1-3/8"	Part number	Head Dia of Torch	Torch Model Number	Fits
ESAB Hypertherm Miller Thermadyne	61-1.007	.750 to 1.005 Straight Hole	250, 380, 650  Air T30, Duramax, Duramax HRT/HRTs, Duramax HRT2, Duramax LT, Duramax MRT, Duramax RT, PAC105, PAC110, PAC120, PAC121, PAC123, PAC125, PAC140, RT60, RT80, T100, T30V, T45V, T60, T80  ICE-27  SL-40	PG-601 & 30061
Hypertherm Miller	61-1.070	1.030 to 1.068	PAC130; PAC160  ICE-40C, ICE-40T, ICE-50C, ICE-55C, ICE-60T, ICE-80T, Spectrum 875	PG-601 & 30061
ESAB Hypertherm Lincoln Miller Thermadyne	61-1.200	1.069 to 1.195 Straight Hole	900,1300,1600, PT-27 or I-750, I-1000  PAC135  LC-25, LC-40  Spectrum 500, 750, XT-30C, XT-40  SL-60, SL-100, RPT-100 (New #1), Drag-Gun, Cutmaster 50, 52, 100, 102, PCH 42	PG-601 & 30061
Hypertherm Lincoln	61-1.275	1.199 to 1.270	Power Max 1000, PAC135  Lincoln 125, PGT 125 Torch	PG-601 & 30061
Hypertherm Bushing O.D. 1-1/2"	64-1.380	1.35 to 1.375	Duramax Hyamp	Special Order
Thermadyne Bushing O.D. 1-7/8"	62-1.430	1.400 to 1.425	PCH-120 Torch (Special) Larger head diameter on heat shield	Special Order

## GENERAL PLASMA BUSHING SIZE INFORMATION

Head Dia of Torch	.750 to 1.005 Straight Hole	1.030 to 1.068	1.069 to 1.195 Straight Hole	1.199 to 1.270	1.350 to 1.375	1.400 to 1.425
Plasma Bushing	61-1.007	61-1.070	61-1.200	61-1.275	64-1.380 Special	62-1.430 Special
Plasma Wiz	30061-1.007	30061-1.070	30061-1.200	30061-1.275	N/A	N/A
Plasma Cutting Guide	PG-601-1.007	PG-601-1.070	PG-601-1.200	PG-601-1.275	PG-604 Special	PG-602 Special